



A-5. Vibratory extraction of nearshore pipeline segment.



A-6. Broken pipe after one of three unsuccessful attempts at vibratory extraction.